


**General guidance for measuring a door curvature.**



Please note that the drawing show the different types of grooves only - the construction of the boards may differ.

O.H.Industri A/S  
 Smedevej 17  
 DK - 7430 Ikast  
 +45 9725 1200  
[www.oh-industri.com](http://www.oh-industri.com)

Made: 12.03.2014	Data sheet: PMN	Draw.: HMN
Revised: 19.01.2017	Data sheet: CRS	Draw.: HMN/CRS